


2+108
BOTZ

TILE RECORD MAP

Moore Farms



NAME Bob Wood

Section _____ Township _____ County _____

Contractor _____ Date installed _____

Amount of tile installed 5" _____ 6" _____ 8" _____
 10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4330